



**Program for the Training-Course  
FMS (Advanced Training)  
March 26<sup>th</sup> to March 30<sup>th</sup>, 2012**

**1<sup>st</sup> day – Burner Control Unit FMS / VMS**

10:00 hr	Welcome
10:45 hr	Bruner Control Unit (FMS)
12:45 hr	Lunch
13:45 hr	Bruner Control Unit (FMS)
17:00 hr	End of the first day

**2<sup>nd</sup> day – Burner Control Unit FMS / VMS**

08:30 hr	Bruner Control Unit (FMS)
12:45 hr	Lunch
13:30 hr	Bruner Control Unit (FMS)
17:00 hr	End of the second day
19:00 hr	<b>Wine tasting</b>

**3<sup>rd</sup> day – Burner Control Unit (FMS / Flame Scanners /  
O<sub>2</sub>-measurement (LT 2 / LS 2 and LT 1 / LS 1)**

08.30 hr	Bruner Control Unit (FMS)
12:45 hr	Lunch
13:45 hr	Flame Scanners (Monitoring)
15:30 hr	O <sub>2</sub> -measurement (LT 2 / LS 2 and LT 1 / LS 1)
17:00 hr	End of the third day



**Program for the Training-Course  
FMS (Advanced Training)  
March 26<sup>th</sup> to March 30<sup>th</sup>, 2012**

**4<sup>th</sup> day – O<sub>2</sub>-Measurement (LT 2 / LS 2 and LT 1 / LS 1)**

<b>08:30 hr</b>	O <sub>2</sub> -measurement (LT 2 / LS 2 and LT 1 / LS 1)
<b>12:45 hr</b>	Lunch
<b>13:45 hr</b>	O <sub>2</sub> -measurement (LT 2 / LS 2 and LT 1 / LS 1)
<b>17:00 hr</b>	End of the fourth day
<b>19:00 hr</b>	<b>Dinner</b>

**5<sup>th</sup> day – Integrated O<sub>2</sub>-Control**

<b>08:30 hr</b>	Integrated O <sub>2</sub> -control
<b>12:00 hr</b>	Lunch
<b>13:00 hr</b>	Integrated O <sub>2</sub> -control
<b>ca. 15:00 hr</b>	End of the Training Course